

## Parts Bulletin

NO.	263
MODEL <b>Eq</b> i	All Kohler EFI uipped Engines
DATE ISSUED	DATE REVISED
7/15	4/18

## EFI Diagnostic Software 25 761 23-S - SOFTWARE UPDATE

## **UPDATE 11 for Version 2.11 Software**

4/2018

**IMPORTANT:** If you are using Version 2.11 Software

If you are using Version 2.11 of the Diagnostic System for Kohler and the displayed version number (in the lower right of the main screen) is less than 2.11.0011 there is an update to the software that should be installed to provide additional diagnostics for ECH440, ECH940, ECH980, and ELH775 engines. This is a **no-charge** update for 2.11 software users.



To download Update 11, enter the following web site into your web browser address line:


## http://kohler.diagsys.com/


Under the header **Update 11 for Version 2.11 Software**, select "Click Here to Download this update"

link.



Follow the IMPORTANT instructions as listed on the next screen shown below.





At the screen to run or save the update (shown below), CLICK on the downward triangle and choose **SAVE AS** to save this update to your desktop.



Right click the installer icon on your desktop and select "Run as Administrator" to install the software.