

## Parts Bulletin

NO.	259
MODEL (	Courage and Command Twins
DATE ISSUED	DATE REVISED
6/13	10/14

## **DSAI/MDI** Ignition

Kohler 12 volt Digital Spark Advanced Ignition (DSAI) has been discontinued. A new magneto powered spark advance system MDI has taken its place. This new MDI system no longer requires 12 volts to function.

DSAI Ignition System parts and kits will no longer be available. Replacement of current DSAI ignition parts requires an MDI conversion kit. The MDI kits require use of the original engine wire harness.

The following table shows the various DSAI system modules and where they were used. The chart identifies the needed kit to convert to MDI.

After the conversion from DSAI to MDI Ignition, the modules can be replaced individually.

Engine Model	Previous Ignition Module	MDI Module Conversion Kit
CH/CV740	24 584 52-S, 24 584 63-S, 24 584 89-S Ignition Module	25 707 03-S
CH/CV740	24 584 31-S Speed Advance Module	25 707 03-S
CH/CV740	24 755 162-S Kit, 24 755 172-S Kit	25 707 03-S
CH/CV750	24 584 53-S, 24 584 64-S, 24 584 90-S Ignition Module	25 707 03-S
CH/CV750	24 584 38-S, 24 584 39-S Speed Advance Module	25 707 03-S
CH/CV750	24 755 173-S Kit	25 707 03-S
SV735/740/840	24 584 63-S, 24 584 89-S Ignition Module	32 707 01-S
SV735/740/840	24 584 31-S Speed Advance Module	32 707 01-S
SV735/740/840	24 755 162-S Kit, 24 755 172-S Kit	32 707 01-S