

NO.		<b>356</b>
MODEL		<b>ECV850-ECV880, PCV850, PCV860</b>
DATE ISSUED	DATE REVISED	
<b>12/17</b>		

### 90° Fitting Change

A new Breather Restrictor Kit has been released for use on any ECV850-ECV880, PCV850, or PCV860 engine where excess oil consumption is observed through both cylinders and the breather is believed to be suspect.

The kit has a new design 90° fitting that features a restrictor orifice that is molded into the part. This design reduces the amount of vacuum being pulled through the breather system and reduces the amount of oil being consumed.

This kit is backwards compatible and is available from your Kohler source of supply. Order part number 19 755 17-S.

Engines with Serial Number 4722804211 and later are built with the new restrictor fitting.

Specifications ECV850-3021 and ECV860-3026 have only been built with the new restrictor fitting.

Normal warranty terms apply. Submit a warranty claim using 19 294 04 as the Defective Part Number and ZZ (Other) as the Failure Code. Labor time of up to 0.3 hour using Labor Code 9999 for Misc. Labor.

Routing	Service Manager	Sales Manager	Parts Manager	Chief Mechanic	Mechanic No. 1	Mechanic No. 2	Mechanic No. 3	Mechanic No. 4	Return This To
Initial Here									